

POLYTOP

Exporter from china

PTF2-3E Functions of digital readout (a universal model for spark [EDM] machine tools)



- Metric system/British system conversion
- Power down memory
- Mid-splitting function
- Control mode setting function
- PCD hole positioning on circumference
- Restoring height setting function
- 200 groups zero position memory
- Zero position automatic digital follow-up
- Up to target values control